

Bollettino unificazione Pompe acqua / Water pump unification news letter

Codici coinvolti / involved parts number

METELLI	GRAF	KWP	Make	ADAPTABLE TO OE
24-0762	PA762	10762	AUDI / SEAT / SKODA / VOLKSWAGEN	1100635 / 038 121 011C / 038 121 011D / 03L 121 001B / 03L 121 011B
24-0878	PA878	10878	AUDI / FORD EUROPE / SEAT / SKODA / VOLKSWAGEN / VOLKSWAGEN LCV	038 121 011J / 1310015 / 1457395 / 038 121 011G
24-0905	PA905	10905	AUDI / CHRYSLER / DODGE / JEEP / MITSUBISHI / SEAT / SKODA VOLKSWAGEN	68000693AB / MN980266 / 68000693AC / 68000693AA / 038 121 011K / 038 121 011H / MN980134

24-0762/ PA762/ 10762



24-0878/ PA878 / 10878



24-0905/ PA905/ 10905



Sono state sostituite da / have been replaced by

24-1355/ PA1355/ 101355



La nuova pompa acqua 24-1355 differisce dalle pompe 24-0878, 24-0905 e 24-0762 solo nel corpo. La freccia evidenzia la forma differente del bordo esterno, che essendo meno ingombrante, non crea problemi di intercambiabilità con i vecchi codici 24-0878, 24-0905 e 24-0762.

The new water pump 24-1355 differs from the water pumps 24-0878, 24-0905 and 24-0762 only in the housing. The arrow highlights the different shape of the external edge, which being less bulky it doesn't give interchangeability problem with the old references 24-0878, 24-0905 and 24-0762.

Bollettino sostituzione pompa acqua / Water pump replacement bulletin

24-1090 / PA1090 / 101090



Ref.	MARCA / MAKE	MODELLO VERSIONE / MODEL -VERSION	ADATTABILE A OE / ADAPTABLE TO OE
24-1090 PA1090 101090	AUDI / MITSUBISHI / SEAT / SKODA / VOLKSWAGEN	A3 II (8P1), Sportback : 2.0 TDi, quattro; 2.0 TDi, quattro, Sportback / A4 III (8EC), Avant : 2.0 TDi, quattro / A4 IV (8K2, K5), Avant : 2.0 TDi; 2.0 TDi, quattro / A4 IV (8KH) Allroad : 2.0 TDi / A5 (8T3), Sportback (8TA), Cabrio (8F7) : 2.0 TDi; 2.0 TDi.....	03G 121 011 / 03L 121 011G / MN980447

SOSTITUITA DA / REPLACED BY

24-1355 / PA1355 / 101355



Ref.	MARCA / MAKE	MODELLO VERSIONE / MODEL -VERSION	ADATTABILE A OE / ADAPTABLE TO OE
24-1355 PA1355 101355	AUDI / MITSUBISHI / SEAT / SKODA / VOLKSWAGEN	A3 I (8L1) : 1.9 TDi; 1.9 TDi quattro / A3 II (8P1) : 2.0 TDi; 2.0 TDi 16V; 2.0 TDi 16V quattro; 2.0 TDi quattro / A3 II Cabrio (8P7) : 2.0 TDi / A3 II Sportback (8PA) : 2.0 TDi; 2.0 TDi 16V; 2.0 TDi 16V quattro; 2.0 TDi quattro / A4 I (8D2, B5) : 1.9 TDi; 1.9 TDi quattro / A4 I Avant (8D5, B5) : 1.9 TDi; 1.9 TDi quattro / A4 II (8E2, B6) : 1.9 TDi; 1.9 TDi quattro / A4 II Avant (8E5, B6) : 1.9 TDi; 1.9 TDi quattro / A4 III (8EC, B7) : 1.9 TDi; 2.0 TDi; 2.0 TDi 16V; 2.0 TDi quattro / A4 III Avant (8ED, B7) : 1.9 TDi; 2.0 TDi; 2.0 TDi 16V; 2.0 TDi quattro / A4 III Cabrio (8H7, B6, 8HE, B7) : 2.0 TDi / A4 IV (8K2, B8) : 2.0 TDi; 2.0 TDi quattro / A4 IV Avant (8K5, B8) : 2.0 TDi; 2.0 TDi quattro / A6 II (4B2, C5) : 1.9 TDi.....	038 121 011K / MN980266 / MN980134 / 68000693AC / 68000693AB / 68000693AA / 1673518 / 1457395 / 1310015 / 1100635 / 03L 121 011B / 038 121 011J / 038 121 011HX / 038 121 011H / 038 121 011DX / 038 121 011D / 038 121 011CX / 038 121 011C / 03L121001B